



Building Solutions That Build Worth

THE CHALLENGE

A large office supply company moved out of this 300,000 square foot building south of Boston mid-way through their lease, leaving a vacant facility. Unfortunately, the building was vandalized and all the high value construction metals were removed.

THE MKR SOLUTION

We were hired to complete the renovation of the property bringing it back into working order. We provided all aspects of building services necessary to restore this structure from exterior landscaping to interior plumbing and electrical service.

- Refuse was removed and all spaces cleaned
- Walls and insulation were patched or replaced
- New guard rails were installed
- Ongoing maintenance of parking lot and security visits to the building were initiated

THE RESULT

The property owners were extremely satisfied with the building's rehabilitation and appearance, and the space is now being shown to prospective tenants.

Suburban Warehouse Facility

